

ATTACHMENT 2
HUD APPENDIX 13.1
Wipe Sampling for Settled
Lead-Contaminated Dust

Appendix 13.1: Wipe Sampling for Settled Lead-Contaminated Dust

Wipe samples for settled leaded dust can be collected from floors (both carpeted and uncarpeted), interior and sash/sill contact areas, and other reasonably smooth surfaces. Wherever possible, hard surfaces should be sampled. Wipe media should be sufficiently durable so that it is not easily torn, but can be easily digested in the laboratory. Recovery rates of between 80-120% of the true value should be obtained for all media used for wipe sampling. Blank media should contain no more than 25 µg/wipe (the detection limit using Flame Atomic Absorption). Additional standards for wipe sampling can be found by consulting ASTM ES 30-94.

1. Wipe Sampling Materials and Supplies

- a. Type of disposable wipe: Any wipe material that meets the following criteria may be used:
 - (i) Contains low background lead levels (less than 5 µg/wipe)
 - (ii) Is a single thickness
 - (iii) Is durable and does not tear easily (do not use Whatman™ filters)
 - (iv) Does not contain aloe
 - (v) Can be digested in the laboratory
 - (vi) Has been shown to yield 80-120% recovery rates from samples spiked with leaded dust (not lead in solution)
 - (vii) Must remain moist during the wipe sampling process (wipes containing alcohol may be used as long as they do not dry out)

Examples of acceptable wipe media include: "Little Ones Baby Wash Cloths™," "Little Ones Baby Wipes Natural Formula™," or "Little Ones Baby Wipes Lightly Scented™," available at K-Mart Stores. This product is also available under the brand names "Pure and Gentle Baby Wipes™" and "Fame Baby Wipes™." Individually-packaged "Wash'n Dri Wipes" are also acceptable. "Wet Wipes," which are available at Walgreens and other stores, may also be used. Other brands are also acceptable if equivalence in both lead contamination (analysis of blanks) and laboratory digestion recoveries (analysis of wipes spiked with known amounts of leaded dust, not lead in solution) can be established. The wipes listed above have proven to be sufficiently durable under field use and to have acceptable recovery rates. Do not use "Little Ones Diaper Wipes," also available at K-Mart stores, or any other brand of wipes for which recovery data have not been established. Do not use wipes that contain aloe. Wipes that contain alcohol may be used as long as they do not dry out during the wipe process.

- b. Non-sterilized non-powdered disposable gloves. Disposable gloves are required to prevent cross-sample contamination from hands.
- c. Non-sterilized polyethylene centrifuge tubes (50 ml size) or equivalent hard-shell container that can be rinsed quantitatively in the laboratory.
- d. Dust sample collection forms contained in these Guidelines
- e. Camera & Film to document exact locations (Optional)
- f. Template Options
 - i. Masking tape. Masking tape is used on-site to define the area to be wiped. Masking tape is required when wiping window sills and window wells in order to avoid contact with window jambs and channel edges. Masking tape on floors is used to outline the exact area to be wiped.
 - ii. Hard, smooth, reusable templates made of laminated paper, metal, or plastic. Note: Periodic wipe samples should be taken from the templates to determine if the template is contaminated. Disposable templates are also permitted so long as they are not used for more than a single surface. Templates must be larger than 0.1 ft², but smaller than 2 ft². Templates for floors are typically 1 ft². Templates are usually not used for windows due to the variability in size and shape (use masking tape instead).
- g. Container labels or permanent marker.
- h. Trash bag or other receptacle (do not use pockets or trash containers at the residence).
- i. Rack, bag, or box to carry tubes (optional)
- j. Measuring tape
- k. Disposable shoe coverings (optional)

2. Single Surface Wipe Sampling Procedure

- a. Outline Wipe Area:

Floors: Identify the area to be wiped. Do not walk on or touch the surface to be sampled (the wipe area). Apply adhesive tape to perimeter of the wipe area to form a square or rectangle of about one square foot. No measurement is required at this time. The tape should be positioned in a straight line and corners should be nominally perpendicular. When putting down any template, do not touch the interior wipe area.

Window sills and other rectangular surfaces: Identify the area to be wiped. Do not touch the wipe area. Apply two strips of adhesive tape across the sill to define a wipe area at least 0.1 square foot in size (approx. 4 inches x 4 inches).

When using tape, do not cross the boundary tape or floor markings, but be sure to wipe the entire sampling area. It is permissible to touch the tape with the wipe, but not the surface beyond the tape.

b. Preliminary inspection of the disposable wipes:

Inspect the wipes to determine if they are moist. If they have dried out, do not use them. When using a container that dispenses wipes through a "pop-up" lid, the first wipe in the dispenser at the beginning of the day should be thrown away. The first wipe may be contaminated by the lid and is likely to have dried to some extent. Rotate the container before starting to ensure liquid inside the container contacts the wipes.

c. Preparation of centrifuge tubes:

Examine the centrifuge tubes and make sure that the tubes match the tubes containing the blind spiked wipe samples. Partially unscrew the cap on the centrifuge tube to be sure that it can be opened. Do not use plastic baggies to transport or temporarily hold wipe samples. The laboratory cannot measure lead left on the interior surface of the baggie.

d. Gloves

Don a disposable glove on one hand; use a new glove for each sample collected. If two hands are necessary to handle the sample, use two new gloves, one for each hand. It is not necessary to wipe the gloved hand before sampling. Use a new glove for each sample collected.

e. Initial placement of wipe:

Place the wipe at one corner of the surface to be wiped with wipe fully opened and flat on the surface.

f. First wipe pass - (side-to-side):

With the fingers together, grasp the wipe between the thumb and the palm. Press down firmly, but not excessively with both the palm and fingers (do not use the heel of the hand). Do not touch the surface with the thumb. If the wipe area is a square, proceed to wipe side-to-side with as many "S"-like motions as are necessary to completely cover the entire wipe area. (See step h for non- square areas.) Exerting excessive pressure on the wipe will cause it to curl. Exerting too

little pressure will result in poor collection of dust. Do not use only the fingertips to hold down the wipe, because there will not be complete contact with the surface and some dust may be missed. Attempt to remove all visible dust from the wipe area.

g. Second wipe pass - (top-to-bottom):

Fold the wipe in half with the contaminated side facing inward. (The wipe can be straightened out by laying it on the wipe area, contaminated side up, and folding it over.) Once folded, place in the top corner of the wipe area and press down firmly with the palm and fingers. Repeat wiping the area with "S"-like motions, but on the second pass, move in a top-to-bottom direction. Attempt to remove all visible dust. Do not touch the contaminated side of the wipe with the hand or fingers. Do not shake the wipe in an attempt to straighten it out, since dust may be lost during shaking.

h. Rectangular areas (e.g. window sills):

If the surface is a rectangle (such as a window sill), two side-to-side passes must be made over half of this surface, the second pass with the wipe folded so that the contaminated side faces inward. For a window sill, do not attempt to wipe the irregular edges presented by the contour of the window channel. Avoid touching other portions of the window with the wipe. If there are paint chips or gross debris in the window sill, attempt to include as much of it as possible on the wipe. If all of the material cannot be picked up with one wipe, field personnel may use a second wipe at their discretion and insert it in the same container. Consult with the analytical laboratory to determine if they can perform analysis of two wipes as a single sample. When performing single-surface sampling, do not use more than two single surface wipes for each container. If heavily dust-laden, a smaller area should be wiped. It is not necessary to wipe the entire window well but do not wipe less than 0.10 ft² (approx 4" x 4").

i. Packaging the Wipe:

After wiping, fold the wipe with the contaminated side facing inward again, and insert aseptically (without touching anything else) into the centrifuge tube or other hard-shelled container. If gross debris is present, such as paint chips in a window well, make every attempt to include as much of the debris as possible in the wipe.

j. Labelling the Centrifuge tube:

Seal the tube and label with the appropriate identifier. Record the laboratory submittal sample number on the field sampling form (see Chapters 5 and 14).

k. Area Measurement:

After sampling, measure the surface area wiped to the nearest eighth of an inch using a tape measure or a ruler. The size of the area wiped must be at least 0.10 ft² in order to obtain an adequate limit of quantitation (25 µg/wipe is the typical detection limit with flame AA; 25 µg/0.10 square feet = 250 µg/ft², which is half of the HUD clearance criterion for interior window sills). No more than 2 square feet should be wiped with the same wipe or else the wipe may fall apart. Record specific measurements for each area wiped on the field sampling form.

l. Form Completion

Fill out the appropriate field sampling forms (see Form 5.4 or Form 14.2 in these Guidelines) completely. Collect and maintain any field notes regarding type of wipe used, lot number, collection protocol, etc.

m. Trash Disposal:

After sampling, remove the masking tape and throw it away in a trash bag. Remove the glove; put all contaminated gloves and sampling debris used for the sampling period into a trash bag. Remove the trash bag when leaving the dwelling. Do not throw away gloves or wipes inside the dwelling unit where they could be accessible to young children, resulting in a suffocation hazard.

Repeat steps a. through m. for additional samples in the same dwelling unit.

3. Composite Wipe Sampling

Whenever composite sampling is contemplated, consult with the analytical laboratory to determine if the laboratory is capable of analyzing composite samples. When conducting composite wipe sampling, the procedure stated above should be used with the following modifications:

When outlining the wipe areas (step a), set up all of the areas to be wiped before sampling. The size of these areas should be roughly equivalent, so that one room is not over-sampled.

After preparing the centrifuge tube, put on the glove(s) and complete the wiping procedures for all subsamples (steps e-i). A separate wipe must be used for each area sampled. After wiping each area, carefully insert the wipe sample into the same centrifuge tube (no more than 4 wipes per tube).

Once all subsamples are in the tube, label the tube. Record a separate measurement for each area that is subsampled on the field collection form (see Form 5.4a or Form 14.2a

for a sample form). Finally, complete trash disposal (step m), making sure that no masking tape is left behind.

Risk assessors and inspector technicians do not have to remove their gloves between subsample wipes for the same composite sample as long as their gloved hands do not touch an area outside of the wipe areas. If a glove is contaminated, the glove should be immediately replaced with a clean glove.

In addition to these procedural modifications, the following rules for compositing should be observed:

- Separate composite samples are required from carpeted and hard surfaces (*e.g.*, a single composite sample should not be collected from both carpeted and bare floors).
- Separate composite samples are required from each different component sampled (*e.g.*, a composite sample should not be collected from both floors and window sills).
- Separate composite samples are required for each dwelling

4. Blank Preparation

After sampling the final dwelling unit of the day, but before decontamination, field blank samples should be obtained. Analysis of the field blank samples determines if the sample media is contaminated. Each field blank should be labeled with a unique identifier similar to the others so that the laboratory does not know which sample is the blank (*i.e.*, the laboratory should be "blind" to the blank sample).

Blank wipes are collected by removing a wipe from the container with a new glove, shaking the wipe open, refolding as it occurs during the actual sampling procedure, and then inserting it into the centrifuge tube without touching any surface or other object. One blank wipe is collected for each dwelling unit sampled or, if more than one dwelling unit is sampled per day, one blank for every 50 field samples, whichever is less. Also, collect one blank for every lot used. Record the lot number.

5. Inspector Decontamination:

After sampling, wash hands thoroughly with plenty of soap and water before getting into car. A bathroom in the dwelling unit may be used for this purpose, with the owner's or resident's permission. If there is no running water in the dwelling unit, use wet wipes to clean the hands. During sampling, inspectors must not eat, drink, smoke, or otherwise cause hand to mouth contact.

6. Spike Sample Submission

Samples spiked with a known amount of leaded dust should be inserted into the sample stream randomly by the person conducting field sampling to determine if there is

adequate quality control of the digestion process at the laboratory. Dust-spiked wipe samples should be submitted blindly to the laboratory by the individual performing field sampling at the rate of no less than one for every fifty field samples. Any laboratory can spike wipe samples using the procedure in Appendix 14.3. The laboratory performing the analysis of the field samples can also prepare the spike sample as long as the person performing the field sampling makes the spike sample indistinguishable from the field samples. The person conducting the field sampling should take the spike sample prepared in the laboratory and relabel the container with an identifier similar to the other field samples. The spike sample wipe should not be put into another container. Spike samples should be made using the same lot as that used in the field.

A dust-spiked sample is defined as a wipe or filter containing a known weight of lead-based paint dust, measured to the nearest 0.1 μg of leaded dust. A dust-spiked sample is prepared in a laboratory with the amount of lead-based dust present being between 50 - 1000 μg . For wipe samples, labs should use NIST Standard Lead Paint Dust (Standard 1578) or an equivalent secondary standard. See Appendix 14.3 for further details.

7. Field Qualifications of Dust Sampling Technicians

All individuals performing dust sampling should have state-certified training. Where possible, field experience in environmental sampling is preferable.

8. Quality Assurance/Quality Control

Blind analysis of spiked samples must fall within 80% - 120% of the true value. If the laboratory fails to obtain readings within the QA/QC error limits:

- a. Two more spikes should be sent immediately to the lab for analysis.
- b. If the two additional spike samples fail, the sample batch should be considered invalid. A full review of laboratory procedures may be necessary. Additional samples may need to be collected from the dwelling units from locations near the locations previously sampled.

If more than 50 $\mu\text{g}/\text{wipe}$ is detected in a blank sample, the samples should be collected again since the media is contaminated. Blank correction of wipe samples is not recommended.

9. Other Information

See Chapter 5 and Chapter 14 for additional information on dust wipe sampling. Also see "Residential Sampling for Lead: Protocols for Leaded Dust and Soil Sampling" from EPA and ASTM E84-94 for further information.